

Road bike stabilizer Applications

| BIKE | Year | Road Stabilizer Kit Number | Road Mount Kit Number | Triple clamp Mount TCM | Triple clamp nut TCM | Frame Bracket FBR | Linkarm LKM | reversed position | Parts in kit |
|-----------------------|---------|---------------------------------|-------------------------------------|-----------------------------|----------------------|-------------------|-------------|-------------------|--------------|
| Aprilia | | | | | | | | | |
| RSV Mille and "R" | 2000-02 | RS-37-2238-35F | RM-37-2238 | 22-2925-00 | 2910-1422 | 22-6036-03 | 4031-35 | | RH-111 |
| RXV / SVX 450/550 * | 2007-11 | DS-4551-10 | DM-4551-10 | 106 40 31 | not used | FBD-4551-00 | 4032-40 | | parts |
| BMW | | | | | | | | | |
| BMW HP2 | 2006-10 | DS-SUB-6032-14 | DM-SUB-6032-14 | 22-2918-00 | stock | FBD-6032 | 4032-35 | x | parts |
| BMW G650X * | 2007-10 | DS-4554-10 | DM-4554-10 | 90 40 41 | not used | FBD-4554-00 | 4032-40 | | |
| BMW F650GS | 2009-10 | working on this | send email requests | | | | | | |
| BMW F800GS | 2008-11 | DS-SUB-6504-28 | DM-SUB-6504-28 | SUB-09806-P3 | not used | 22-6504-28 | 4032-35 | x | parts |
| BMW 1200 GS/GSA | 2008-11 | working on this | send email requests | SUB-08826-10 | not used | 22-0020-00 | 4031-396 | | parts |
| Ducati | | | | | | | | | |
| Monster 600/750/900 | 1999-01 | RS-28-0020-40F | RM-28-0020 | 80 32 35 | none | 22-5455-06 | 4031-40 | | RH-114 |
| Monster 696 | 2008-10 | RS-76-3266-40S | RM-76-3266 | 64 40 40 | BMS-40-0038R-10 | 22-5037-14 | 4032-40 | | RH-132 |
| Monster 796 | 2011-12 | RS-75-3367-40S | RM-75-3367 | 82 40 40 | BMO-40-0058R-10 | 22-5057-14 | 4032-40 | | RH-133 |
| Monster 1100 | 2009-10 | RS-75-3166-40S | RM-75-3166 | 82 40 40 | BMO-40-0038R-10 | 22-5037-14 | 4032-40 | | RH-132 |
| Monster 1100 Evo | 2011-12 | RS-75-3367-40S | RM-75-3367 | 82 40 40 | BMO-40-0058R-10 | 22-5057-14 | 4032-40 | | RH-133 |
| 748 / 916 / 996 / 998 | 1997-02 | RT-4053-00 | RM-31-0000 | TCR-4053-00 | none | none | 4031-58 | | parts |
| Hypermotard 796 | 2009-12 | RS-58-3554-45R | RM-58-3554 | SUB-08313-00-0 | BMO-1125-875K | 22-5425-13 | 4032-45 | x | RH-135 |
| Hypermotard 1100 & S | 2008-09 | RS-58-0054-45R | RM-58-0054 | SUB-08313-00-0 | none | 22-5425-13 | 4032-45 | x | RH-125 |
| Hypermotard 1100 Evo | 2010-12 | RS-58-0054-45R | RM-58-0054 | SUB-08313-00-0 | none | 22-5425-13 | 4032-45 | x | RH-125 |
| Hypermotard Evo SP | 2010-12 | RS-73-0054-45R | RM-73-0054 | SUB-08313-00-1 | none | 22-5425-13 | 4032-45 | x | RH-125 |
| Hypermotard Evo +12 | 2010-12 | RS-74-0054-45R | RM-74-0054 | SUB-08313-00-2 | none | 22-5425-13 | 4032-45 | x | RH-125 |
| Honda | | | | | | | | | |
| CBR 600 F4 | 1999-00 | RS-15-1317-40F | RM-15-1317 | 22-3520-00 | 2410-3017 | 22-4943-13 | 4031-40 | | RH-100 |
| CBR 600 F4i | 2001-07 | RS-15-1317-40F | RM-15-1317 | 22-3520-00 | 2410-3017 | 22-4943-13 | 4031-40 | | RH-100 |
| CBR 600 RR | 2003-04 | RS-15-1340-40F | RM-15-1340 | 22-3520-00 | 2410-3017 | 22-4023-04 | 4031-40 | | RH-103 |
| CBR 600 RR | 2005-06 | RS-46-2540-40F | RM-46-2540 | 22-3520-10 | 2410-3013 | 22-4023-04 | 4031-40 | | RH-103 |
| CBR 900 RR | 1996-97 | RS-15-1316-40F | RM-15-1316 | 22-3520-00 | 2410-3017 | 22-4920-10 | 4031-40 | | RH-101 |
| CBR 900 RR | 1998-99 | RS-15-1318-40F | RM-15-1318 | 22-3520-00 | 2410-3017 | 22-4920-16 | 4031-40 | | RH-101 |
| CB 919 (CB900F) | 2002-07 | RS-61-0060-40S | RM-61-0060 | 100 32 32 | none | FBD-4551-00 | 4032-40 | | Parts |
| CB 1000R | 2012 | working on this | send email requests | | | | | | |
| CBR 929 | 2000-01 | RS-15-1315-40F | RM-15-1315 | 22-3520-00 | 2410-3017 | 22-4820-11 | 4031-40 | | RH-100 |
| CBR 954 | 2002-03 | RS-15-1332-40F | RM-15-1332 | 22-3520-00 | 2410-3017 | 22-4826-07 | 4031-40 | | RH-100 |
| RC51 | 2000-01 | RS-15-1313-40F | RM-15-1313 | 22-3520-00 | 2410-3017 | 22-4015-15 | 4031-40 | | RH-100 |
| RC51 | 2002-06 | RS-33-2434-40F | RM-33-2434 | 22-4617-00 | 3310-4112 | 22-4023-14 | 4031-40 | | RH-101 |
| VFR 800 (Interceptor) | 1998-10 | RS-15-1314-40F | RM-15-1314 | 22-3520-00 | 2410-3017 | 22-4025-07 | 4031-40 | | RH-100 |
| VTR 1000 (Superhawk) | 1997-05 | RS-15-1314-40F | RM-15-1314 | 22-3520-00 | 2410-3017 | 22-4025-07 | 4031-40 | | RH-100 |
| VFR 1200 | 2010-11 | possible | send emails | | | | | | |
| Kawasaki | | | | | | | | | |
| EX-250R (Ninja 250R)* | 1997-07 | RS-60-0053-40R | RM-60-0053 | 22-1626-00 | none | FBD-4554-80 | 4032-40 | x | Parts |
| EX-250R (Ninja 250R)* | 2008-11 | RS-60-0058-40S | RM-60-0058 | 22-1626-00 | none | FBD-4558-00 | 4032-40 | | Parts |
| ER-6N | 2009-10 | new barclamp | send emails | | | | | | |
| EX-650R (Ninja 650R)* | 2006-08 | RS-56-0053-40F | RM-56-0053 | 90 35 28 | none | FBD-4554-80 | 4031-40 | | Parts |
| EX-650R (Ninja 650R)* | 2009-10 | new barclamp | send emails | | | | | | |
| ZZR-600 | 2003-08 | RS-12-1029-45F | RM-12-1029 | 22-3422-10 | 2210-3016 | 22-9934-08 | 4031-45 | | RH-115 |
| ZX-6R | 1998-99 | RS-14-1029-45F | RM-14-1029 | 22-3422-30 | 2210-3016 | 22-9934-08 | 4031-45 | | RH-115 |
| ZX-6R | 2000-02 | RS-12-1029-45F | RM-12-1029 | 22-3422-10 | 2210-3016 | 22-9934-08 | 4031-45 | | RH-115 |
| ZX-6R / ZX-6RR | 2003-04 | RS-35-1736-40F | RM-35-1736 | 22-4125-00 | 2510-3615 | 22-0041-16 | 4031-40 | | RH-104 |
| ZX-6R / ZX-6RR ** | 2005-06 | RS-50-2145-45F | RM-50-2145 | 22-4124-00 | 2810-3617 | 22-6142-02 | 4031-45 | | RH-122 |
| ZX-6R | 2007-08 | RS-54-2752-45F | RM-54-2752 | 22-2825-10 | 2810-3212 | 22-9040-06 | 4031-45 | | RH-102 |
| ZX-6R | 2009-11 | RS-64-2761-45F | RM-64-2761 | 22-2826-00 | 2810-3212 | 22-9032-17 | 4031-45 | | RH-128 |
| ZX-7R | 1996-03 | RS-24-1729-40F | RM-24-1729 | 22-4122-10 | 2510-3615 | 22-9934-08 | 4031-40 | | RH-100 |
| ZX-9R | 1998-99 | RS-21-1529-40S | RM-21-1529 | 22-3623-00 | 2510-3230 | 22-9934-08 | 4032-40 | | RH-100 |
| ZX-9R | 2000-03 | RS-16-1129-40R | RM-16-1129 | 22-3522-00 | 2210-3019 | 22-9934-08 | 4032-40 | x | RH-100 |
| Z-750S | 2006-07 | RS-43-0031-40F | RM-43-0031 | 118 34 23 | none | FBD-4557-00 | 4031-40 | | Parts |
| Z-1000 | 2003-08 | RS-43-0031-40F | RM-43-0031 | 118 34 23 | none | FBD-4557-00 | 4031-40 | | Parts |
| ZX-10R | 2004-05 | RS-44-2142-45F | RM-44-2142 | 22-4125-10 | 2810-3617 | 22-9027-14 | 4031-45 | | RH-118 |
| ZX-10R | 2006-07 | RS-51-2749-45F | RM-51-2749 | 22-2825-00 | 2810-3212 | 22-9020-28 | 4031-45 | | RH-126 |
| ZX-10R | 2008-10 | RS-51-2949-45F | RM-51-2949 | 22-2825-00 | use stock | 22-9020-28 | 4031-45 | | RH-126 |
| ZX-10R | 2011 | Working on this | Due end of Nov | send emails | | | | | |
| ZX-12R** | 2000-01 | RS-30-2033-40F | RM-30-2033 | 22-3621-00 | 2210-3232 | 22-5040-15 | 4031-40 | | RH-119 |
| ZX-12R** | 2002-05 | RS-47-2633-40F | RM-47-2633 | 22-4122-80 | 2510-3617 | 22-5040-15 | 4031-40 | | RH-119 |
| ZX-14 ** | 2006-11 | RS-53-2851-40F | RM-53-2851 | 22-2532-00 | 2510-3214 | 22-6154-00 | 4031-40 | | RH-124 |
| ZX-14 | 2012 | All new kit | send emails | | | | | | |
| ZRX-1100* | 1999-00 | RS-34-0030-40R | RM-34-0030 | 90 34 12 25 | Not Used | FBD-4555-00 | 4032-40 | x | RH-105 |
| ZRX-1200 * | 2001-05 | RS-34-0030-40R | RM-34-0030 | 90 34 12 25 | Not Used | FBD-4555-00 | 4032-40 | x | RH-105 |

* Models listed with one asterik require very minor welding of the frame bracket to the frame.

** Models with 2 asteriks require drilling and or tapping the frame / drills, tap and instructions included.

Continued on next page

Road bike stabilizer Applications

| BIKE | Year | Road Stabilizer Kit Number | Road Mount Kit Number | Triple clamp Mount TCM | Triple clamp nut TCN | Frame Bracket FBR | Linkarm LKM | reversed position | Parts in kit |
|---|---------|---------------------------------------|-----------------------|------------------------|----------------------|-------------------|-------------|-------------------|--------------|
| MV Agusta Brutale | 2006-09 | RS-70-0065-45R | RM-70-0065 | 22-0020-80 | Not Used | 22-5319-14 | 4032-45 | x | RH-131 |
| Ktm | | | | | | | | | |
| 640 Duke & Duke II | 2001-07 | RS-62-0060-40S | RM-62-0060 | 90 40 34 | Not Used | FBD-4551-00 | 4032-40 | | Parts |
| 690 Duke & R | 2008-11 | DS-5972-00 | DM-5972-00 | 90 40 41 | none used | FBD-5972 | 4032-40 | | Parts |
| 690 SM / SMC | 2007 | DS-5972-00 | DM-5972-00 | 90 40 41 | none used | FBD-5972 | 4032-40 | | Parts |
| 690 SM / SMR | 2008 | DS-5972-00 | DM-5972-00 | 90 40 41 | none used | FBD-5972 | 4032-40 | | Parts |
| 690 SMC / Enduro | 2008-12 | DS-SUB-3528 | DM-SUB-3528 | SUB-03016-103 | none used | FBD-3528 | 4032-40 | | Parts |
| 950/ 990 Adventure | 2003-12 | DT-SUB-3530 | DM-SUB-3530 | none used | none used | FBD-3530 | 4032-40 | | Parts |
| 950/ 990 Super Duke | 2005-12 | RS-59-0056-40F | RM-59-0056 | 90 40 36 | Not Used | 22-9945-15 | 4031-40 | | RH-127 |
| 990 Super Duke R | 2008-12 | RS-59-0056-40F | RM-59-0056 | 90 40 36 | Not Used | 22-9945-15 | 4031-40 | | RH-127 |
| 950 SE Super Enduro | 2007-10 | DT-SUB-3544 | DM-SUB-3544 | none used | none used | FBD-3544 | 4032-40 | | Parts |
| 950/ 990 SM | 2005-09 | DT-SUB-3545-28 | DM-SUB-3545-28 | none used | none used | FBD-3545 | 4032-40 | | Parts |
| 950/ 990 SMR | 2007-08 | DT-SUB-3545-27 | DM-SUB-3545-27 | none used | none used | FBD-3545 | 4032-40 | | Parts |
| 990 SMT / SMR | 2010-11 | send emails | | | | | | | |
| Suzuki | | | | | | | | | |
| Bandit 1200 & S * | 1998-05 | RS-29-0046-40S | RM-29-0046 | 90 35 31 | not used | FBD-4554-86 | 4032-40 | | Parts |
| Bandit 1250 & S * | 2007-09 | RS-29-0055-40S | RM-29-0055 | 90 35 31 | not used | FBD-4554-87 | 4032-40 | | Parts |
| DL 650 V-strom | 2004-12 | RS-42-0041-40S | RM-42-0041 | 100 35 43 | not used | 22-5090-65 | 4032-40 | | RH-117 |
| DL 1000 V-strom | 2002-09 | RS-42-0041-40S | RM-42-0041 | 100 35 43 | not used | 22-5090-65 | 4032-40 | | RH-117 |
| DL 1000 V-strom | 2012 | need info | | | | | | | |
| Gladius | 2009-10 | send emails | | | | | | | |
| GSX 650F * | 2008-11 | RS-63-0060-40S | RM-63-0060 | 80 35 28 | not used | FBD-4551-00 | 4032-40 | | Parts |
| GSX 1250FA | 2011 | RS-29-0055-40S | RM-29-0055 | 90 35 31 | not used | FBD-4554-87 | 4032-40 | | Parts |
| GSXR 600 | 1997-00 | RS-17-1423-40R | RM-17-1423 | 22-3622-00 | 2415-3214 | 22-7040-13 | 4032-40 | x | RH-100 |
| GSXR 600 | 2001-03 | RS-18-1425-40F | RM-18-1425 | 22-3622-10 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 600 | 2004-05 | RS-17-1425-40F | RM-17-1425 | 22-3622-00 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 600 | 2006-09 | RS-48-2148-45F | RM-48-2148 | 22-4121-00 | 2810-3617 | 22-9938-15 | 4031-45 | | RH-123 |
| GSXR 600 | 2011 | RS-77-3468-45F | RM-77-3468 | 22-2822-00K | 2810-3212K | 22-8641-00K | 4031-45 | | RH-134 |
| GSXR 750 | 1996-99 | RS-17-1423-40R | RM-17-1423 | 22-3622-00 | 2415-3214 | 22-7040-13 | 4032-40 | x | RH-100 |
| GSXR 750 | 2000-03 | RS-18-1425-40F | RM-18-1425 | 22-3622-10 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 750 | 2004-05 | RS-17-1425-40F | RM-17-1425 | 22-3622-00 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 750 | 2006-09 | RS-48-2148-45F | RM-48-2148 | 22-4121-00 | 2810-3617 | 22-9938-15 | 4031-45 | | RH-123 |
| GSXR 750 | 2011 | RS-77-3468-45F | RM-77-3468 | 22-2822-00K | 2810-3212K | 22-8641-00K | 4031-45 | | RH-134 |
| GSXR 1000 | 2001-02 | RS-20-1425-40F | RM-20-1425 | 22-3622-40 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 1000 | 2003-04 | RS-40-2125-40F | RM-40-2125 | 22-4122-60 | 2810-3617 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 1000 | 2005-06 | RS-48-2125-40F | RM-48-2125 | 22-4121-00 | 2810-3617 | 22-8647-00 | 4031-40 | | RH-100 |
| GSXR 1000 | 2007-08 | RS-48-2150-45F | RM-48-2150 | 22-4121-00 | 2810-3617 | 22-9939-15 | 4031-45 | | RH-123 |
| GSXR 1000 | 2009-11 | RS-66-2162-40F | RM-66-2162 | 22-4123-00 | 2810-3617 | 22-8030-32 | 4031-40 | | RH-109 |
| GSXR 1300 (stock TC) | 1999-11 | RS-49-0043-45F | RM-49-0043 | 22-0024-80 | none | 22-7051-13 | 4031-45 | | RH-120 |
| The above kit fits the stock triple clamp WITH the top vibration plate in place. (For bikes with the vibration plate removed use kit # RS-19-1423-45F or RM-19-1423) | | | | | | | | | |
| GSXR 1300 no top plate | 1999-11 | RS-19-1423-45F | RM-19-1423 | 22-3622-30 | 2415-3214 | 22-7040-13 | 4031-45 | | RH-100 |
| The above kit fits the stock triple clamp WITHOUT the top vibration plate in place. | | | | | | | | | |
| SV 650 standard bars | 1999-02 | RS-28-2326-40F | RM-28-2326 | 80 32 35 | 32-3034T-10 | 22-8680-00 | 4031-40 | | RH-107 |
| SV 650 standard bars | 2003-11 | RS-39-0026-40S | RM-39-0026 | 80 35 25 | none | 22-8680-00 | 4032-40 | | RH-108 |
| SV 650 Conv to Clip On | 1999-02 | RS-13-1025-40F | RM-13-1025 | 22-3422-20 | 2210-3016 | 22-8647-00 | 4031-40 | | RH-100 |
| SV 650 Conv to Clip On | 2003-11 | RS-41-0025-40F | RM-41-0025 | 22-0023-80 | None | 22-8647-00 | 4031-40 | | RH-107 |
| SV 650 w/tank spacers | 1999-02 | RS-13-1035-40F | RM-13-1035 | 22-3422-20 | 2210-3016 | 22-8632-00 | 4031-40 | | RH-100 |
| SV 650 w/tank spacers | 2003-11 | RS-41-0035-40F | RM-41-0035 | 22-0023-80 | None | 22-8632-00 | 4031-40 | | RH-107 |
| SV 650S clip ons stk | 2001-02 | RS-32-1025-40F | RM-32-1025 | 22-3422-40 | 2210-3016 | 22-8647-00 | 4031-40 | | RH-100 |
| SV 650S clip ons stk | 2003-11 | RS-19-1425-40F | RM-19-1425 | 22-3622-30 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| SV 650S w/tank spacers | 2001-02 | RS-32-1035-40F | RM-32-1035 | 22-3422-40 | 2210-3016 | 22-8632-00 | 4031-40 | | RH-100 |
| SV 650S w/tank spacers | 2003-11 | RS-19-1435-40F | RM-19-1435 | 22-3622-30 | 2415-3214 | 22-8632-00 | 4031-40 | | RH-100 |
| SV 1000 Standard Bars | 2003-05 | Pull individual parts | | 100 35 26 | None | 22-8680-00 | 4032-40 | | RH-108 |
| SV 1000S clip ons stk | 2003-07 | RS-19-1425-40F | RM-19-1425 | 22-3622-30 | 2415-3214 | 22-8647-00 | 4031-40 | | RH-100 |
| SV 1000S w/tank spacers | 2003-07 | RS-19-1435-40F | RM-19-1435 | 22-3622-30 | 2415-3214 | 22-8632-00 | 4031-40 | | RH-100 |
| TL 1000 R | 1998-03 | RS-17-1423-50R | RM-17-1423 | 22-3622-00 | 2415-3214 | 22-7040-13 | 4032-50 | x | RH-100 |
| TL 1000 S | 1997-01 | RS-17-1422-50R | RM-17-1422 | 22-3622-00 | 2415-3214 | 22-7040-00 | 4032-50 | x | RH-100 |

* Models listed with one asterik require very minor welding of the frame bracket to the frame.

** Models with 2 asteriks require drilling and or tapping the frame / drills, tap and instructions included.

Continued on next page



2625 Honolulu Ave • Montrose, CA 91020 • 818 248-6747 • Fax: 818 248-4529
 www.scottsonline.com • e-mail: sales@scottsonline.com

Road bike stabilizer Applications

| BIKE | Year | Road Stabilizer Kit Number | Road Mount Kit Number | Triple clamp Mount TCM- | Triple clamp nut TCN- | Frame Bracket FBR | Linkarm LKM- | reversed position | Parts in kit |
|-------------------------|---------|----------------------------------|-----------------------------|-------------------------|-----------------------|-------------------|--------------|-------------------|--------------|
| Triumph | | | | | | | | | |
| Daytona 675 | 2006-11 | RS-69-3064-40R | RM-69-3064 | 22-2523-00 | 2510-3209 | 22-6146-00 | 4032-40 | x | RH-130 |
| Street Triple 675 & R | 2008-12 | RS-72-0064-40R | RM-72-0064 | SUB-09325-00 | none | 22-6146-00 | 4032-40 | x | RH-130 |
| TT600 | 2000-03 | RS-11-1010-40F | RM-11-1010 | 22-3421-00 | 2210-3016 | 22-0022-20 | 4031-40 | | RH-112 |
| Triumph Tiger 800xc | 2012 | working on this | send emails | | | | | | |
| Yamaha | | | | | | | | | |
| FZ1 | 2006-11 | working on this | send emails | | | | 4032-?? | | |
| FZ6R | 2009-11 | working on this | send emails | | 2210-2714 | | 4032-?? | | RH-126 |
| YZF-R6 | 1999-00 | RS-23-2121-40F | RM-23-2121 | 22-4122-00 | 2810-3617 | 22-6128-02 | 4031-40 | | RH-109 |
| YZF-R6 | 2001-02 | RS-26-2121-40F | RM-26-2121 | 22-4122-40 | 2810-3617 | 22-6128-02 | 4031-40 | | RH-109 |
| YZF-R6 | 2003-05 | RS-45-2137-45F | RM-45-2137 | 22-4122-70 | 2810-3617 | 22-6134-00 | 4031-45 | | RH-110 |
| YZF-R6 (1 tank bolt) ** | 2006-07 | RS-23-2147-45F | RM-23-2147 | 22-4122-00 | 2810-3617 | 22-9942-02 | 4031-45 | | RH-121 |
| YZF-R6 (1 tank bolt) ** | 2008-11 | RS-23-2157-45F | RM-23-2157 | 22-4122-00 | 2810-3617 | 22-9943-02 | 4031-45 | | RH-121 |
| YZF-R6S (2 tank bolts) | 2006-11 | RS-45-2137-45F | RM-45-2137 | 22-4122-70 | 2810-3617 | 22-6134-00 | 4031-45 | | RH-110 |
| YZF-R1 | 1998-99 | RS-23-2111-40F | RM-23-2111 | 22-4122-00 | 2810-3617 | 22-2929-07 | 4031-40 | | RH-113 |
| YZF-R1 | 2000-03 | RS-23-2112-45F | RM-23-2112 | 22-4122-00 | 2810-3617 | 22-2941-07 | 4031-45 | | RH-113 |
| YZF-R1** | 2004-05 | RS-23-2144-45F | RM-23-2144 | 22-4122-00 | 2810-3617 | 22-9928-02 | 4031-45 | | RH-121 |
| YZF-R1** | 2006 | RS-25-2144-45F | RM-25-2144 | 22-4122-20 | 2810-3617 | 22-9928-02 | 4031-45 | | RH-121 |
| YZF-R1** | 2007-08 | RS-52-2144-45F | RM-52-2144 | 22-4122-90 | 2810-3617 | 22-9928-02 | 4031-45 | | RH-121 |
| YZF-R1 | 2009-11 | RS-68-0063-45F | RM-68-0063 | 22-4222-00 | none | 22-6043-12 | 4031-45 | | RH-129 |
| YZF-R1 | 2012 | New triple clamp | | | | | | | |
| Test only (07-08 R1) | SKF | RS-68-0044-45F | RM-68-0044 | 22-4222-00 | none | 22-9928-02 | 4031-45 | | RH-130 |

* Models listed with one asterik require very minor welding of the frame bracket to the frame.

** Models with 2 asteriks require drilling and or tapping the frame / drills, tap and instructions included.